ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
2

Ward Name
Chowdeshwari Ward

Street ID
I0266, W0264, W0262, W0280

Street Name
NA, Ambedkar Nagar Slum, 2nd Crs, Lakshmi Sagar Lyt

Significant Landmark
NES circle to Kenchenahalli entrance

Segment No.
2/C-I0266/S122023

Total Length (m)
201.08

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	201.08	77.580389	13.109378	77.580926	13.107639	W0262	W0280

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to footpath and Providing RCC covering Slab from NES circle to Kenchenahalli entrance in Ward no 02 of Yelahanka Sub-Division Yelahanka z

Sanctioned Estimated Amount (Rs.)
500000

Sanctioned Year
2014

Year
2014 - 2015

Type of Work
Others

Other Work Type
footpath and Providing RCC covering Slab

Tender
Tender

Work Details
Improvements to footpath and Providing RCC covering Slab from NES circle to Kenchenahalli entrance in Ward no 02 of Yelahanka Sub-Division Yelahanka zone

Job No. / Work Code
002-15-000025

Work Order No.
EE (YNK.D) E-PMT-05/WO/90/2014-15

Work Order Date
18/02/2015

Period of Extention
90 DAYS

Defect Liability Period From
30/04/2015

Defect Liability Period To
29/04/2016

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
H S PALAKSHAMURTHY

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
471877.00

Phone No.

E-Mail ID

9945144999

Field Inspection Details

Number of Trees	Any Other Information	Name
12		RAMANANJEEVAIAH
Date of Inspection	**Remarks**	
22/04/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 2 **Ward Name:** Chowdeshwari Ward **Street ID:** I0266, W0264, W0262, W0280

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	22/04/2017	22/05/2017	COMPLETED
SE	VASU K M	22/04/2017	22/05/2017	COMPLETED
EE	VASU K M	22/04/2017	22/05/2017	COMPLETED
AEE	G.B. PRABHAKAR	22/04/2017	22/05/2017	COMPLETED
AE	RAMANANJEEVAIAH	22/04/2017	22/05/2017	COMPLETED
AE	RAMANANJEEVAIAH	22/04/2017	22/05/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 2 **Ward Name:** Chowdeshwari Ward **Street ID:** I0266, W0264, W0262, W0280